



August 19, 2020

Notice of Recall: All Cam Lock Harnesses

To All Racers, Sanctioning Body Officials, Equipment Wholesalers and Retailers

Recall issued on all camlocks with knurl face plate and Ultra Shield decal on face plate. Does not apply to finger groove face place with Ultra Shield decal or with Ultra Shield engraved on face plate. See photo below for examples. Camlock Buckles with Silver Phillips Head Screws in back plate or Hex (Allen) Drive Screws are good, only back plates screwed on with Black Phillips Head Screws are recalled.

Ultra Shield Race Products will repair or replace at our expense on the above listed belts.

If you have any questions, please do not hesitate to contact us.

Thank you and we apologize for any inconvenience this may have caused.

